

AMS02-PDS

DOC N°: PDS-RP-CGS-060

ISSUE: 1

DATE: 17/09/2008

PAGE : 1 of 1

INSPECTION REPORT

APPLICABLE DOC. REF.

PROC. REF.

AMS02-PDS PFM Manufacturing and Inspection Plan PDS-PL-CGS-001

is. 1

N.A.

ITEM INSPECTED (Name, P/N, S/N) AMS02-PDS PFM – Visual inspection of Distribution Board Assy p/n:11-AMS02PDS-800.00 s/n:01(pcb s/n:A1-2A) – MIP.

REQUIREMENT SATISFIED

Manufacturing according to aerospace standards

INSPECTION (Action/Results)

DESCRIPTION

Inspection was performed at Carlo Gavazzi Space premises starting on 17 September 2008 and was carried out on the following board, detail of the inspected board was below reported:

1) Distribution Board Assy p/n:11-AMS02PDS-800.00 s/n:01(pcb s/n:A1-2A).

HARDWARE REVIEW

1) Distribution Board Assy p/n:11-AMS02PDS-800.00 s/n:01(pcb s/n:A1-2A), Assy:11-AMS02PDS-800.00 rev./, Parts List:11-AMS02PDS-800.01 rev./, Electrical Scheme: 11-AMS02PDS-800.02 rev./, Master PCB:11-AMS02PDS-800.03 rev./.

The following PLVS (Parts List Variation Sheet) was presented during the inspection:

• 11-AMS02PDS-800.01 rev / - A1 can be considered closed.

The board has been cabled according to Internal Cabling Assy 11-AMS02PDS-900.00 rev./.

The H/W has been visually inspected and is ok: no damage, visible clean is ok.

CONCLUSION

The assembled board is in agreement to following documents: Assy 11-AMS02PDS-800.00 rev./, Parts List 11-AMS02PDS-800.01 rev./ and Internal Cabling Assy 11-AMS02PDS-900.00 rev./. The inspection has found no H/W defect.

From the H/W point of view the board can be used to proceed with the next activities:

- Gluing of ring terminal screws and relevant nuts.
- Conformal coating.

	Operator	Quality Assurance	, C.C.
Signature		E. FRANCINI	C. CINQUEPAC
Date		17/09/08 homente	17.5.8